



March 21, 2022

Distribution Partners,

We have become aware that in at least one instance there is a Trylon Cougar safety rail system that has been painted. We would like to remind all our customers that the Cougar rail system inclusive of the aluminum safety rail and the trolley and any other component of the system must not be painted. Applying a coating to any component of the rail system poses a serious safety risk to workers. Please ensure that if a painted rail system or any component thereof is encountered that it is tagged with a warning not to use the system. Should this occur the rail system must be replaced.

Please note that the application of paint to any component of the rail system or the use of a trolley on a painted rail system will result in the warrant being void.

Thank you,

Stocked Product Team

