



November 26, 2019

To all our valued customers,

Trylon has recently received the Safety Notice from Crosby Group regarding potentially defective 7/8" 6.5t Shackles with the PIC marking "5VJ".

Trylon records clearly demonstrate that we did not receive any of the affected Shackles and therefore there is no risk to any previous or current product shipments from Trylon to our customers.

Nonetheless, Trylon has implemented incoming inspections on all Crosby Shackles to prevent any potentially affected product from being received while we work closely with our Supplier to mitigate this risk on their end as well.

Crosby



Production Information Code (PIC) Location

Not Acceptable:

7/8" Crosby
Shackles bearing
the PIC marking
"5VJ".

Regards,

Blake Niemi,
Quality Manager